



# The Jewelry Artists Network

*share, learn, grow*

[www.jewelryartistsnetwork.com](http://www.jewelryartistsnetwork.com)

## Gas/Fuel Temperatures

Acetylene	Oxygen	3300 °C
	Air	2600 °C
Propane	Oxygen	2800 °C
	Air	1950 °C
Hydrogen	Oxygen	2650 °C
	Air	2050 °C
MAPP <sup>®</sup>		2900 °C
Natural Gas		2750 °C
Butane		1760 °C

### A few popular torches:

(There are many other torch variations, this is but a few)

Smith Little Torch	–	Oxy/Propane
Oxy/Acetylene		
SilverSmith	–	Acetylene/Air
Mecco Midget	–	Oxy/Propane
Oxy/Acetylene		
Plumbers Torch	–	Propane/Air
MAPP/Air		
Blazer	–	Butane